



Unassigned Certificate of Inspection

Certificate Number

HV - P 064480 9

It is recommended that this certificate is presented when registering or transferring your vehicle. Until this certificate is presented at a Department of Transport and Main Roads Customer Service Centre, the vehicle registration cannot be transferred online. For more information about online transfers, visit www.qld.gov.au/onlineregotransfer.

Vehicle details

Plate number: CYA28X
 State: Queensland
 VIN/Chassis number: 1HGBH41JXMN109186
 Make: TOYOTA MOTOR CORPORATION
 Model: LS400 20 SER
 Series: EA
 Badge: LX
 Number of cylinders/rotors: 4
 Fuel type: Petrol
 Number of doors: 5
 Engine number: 45578112112
 Compliance type: Compliance Plate
 Date on plate: 1/1997
 Vehicle colour: Silver
 Seating capacity: 5
 Steering position: Centre
 Tare: 3400kg
 GVM: 4500kg

First inspection - Passed Inspection

Odometer reading

43500km

Inspection date and time

10:45 am, 16/04/2016

- ✓ Identification
- ✓ Modification Failed/then passed
- ✓ Seats and Restraints
- ✓ Lights and Electrical Components
- ✓ Windscreen and Windows
- ✓ Body and Chassis
- ✓ Steering and Suspension
- ✓ Wheels and Tyres
- ✓ Brakes components
- ✓ Engines and Drivelines
- ✓ Exhaust Emissions
- ✓ Road Test
- ✓ Service Brake Test: Peak - 75%
Average - 65%
- ✓ Hand brake test: Peak - 85%
Distance - 8m

Inspection Station and Examiner details

AIS name: Kmart Tyre & Auto Service
 AIS number: S38393
 AIS address: Shell Coles Express Service Station
 29 Gailey Road
 St Lucia, QLD, 4068

Name of Examiner: B Nash
 Examiner's number: 2383773
 Mobile AIS Rego No: M29332
 Mobile AIS location: 15 Grand Plaza Drv
 Browns Plains, QLD, 4117

- This certificate or certificate number must be provided to the acquirer of the vehicle at transfer of registration.

Privacy statement: The Department of Transport and Main Roads is collecting this information on this form for the purposes of managing the department's vehicle register. This information is authorised or required by the Transport Operations (Road Use Management) Act. The department or its agents usually gives some or all of this information to vehicle insurers, statutory entities, lawyers, insolvency entities, persons involved in vehicle accidents/incidents or vehicle manufacturers or their employees or agents and to or through interstate registration authorities. Your personal details will not be disclosed to any third party without your consent unless required or authorised by law.



Vehicle details

Plate number: CYA28X
 State: Queensland
 VIN/Chassis number: 1HGBH41JXMN109186
 Make: TOYOTA MOTOR
 Model: CORPORATION
 Body shape: LS400 20 SER
 Series: EA
 Badge: LX
 Number of cylinders/rotors: 4
 Fuel type: Petrol
 Number of doors: 5
 Engine number: 45578112112
 Compliance type: Compliance Plate
 Date on plate: 1/1997
 Vehicle colour: Silver
 Seating capacity: 5
 Steering position: Right
 Tare: 3400kg
 GVM: 4500kg

Inspection Station and Examiner details

AIS name: Kmart Tyre & Auto Service
 AIS number: S38393
 AIS address: Shell Coles Express Service Station, 29 Gailey Road, St Lucia, QLD 4068
 Name of Examiner: B Nash
 Examiner's number: 2383773
 Mobile AIS Rego No: M29332
 Mobile AIS location: 15 Grand Plaza Drv Browns Plains, QLD, 4117

First inspection - Failed Inspection

! Vehicle required for re-inspection within 14 days

If vehicle is not re-inspected within 14 days a new full inspection including payment is required

Odometer reading

43500km

Inspection date and time

10:45 am, 16/04/2016

- ✓ Identification
- ✓ Modification
- ✓ Seats and Restraints
- ✓ Lights and Electrical Components
- ✓ Windscreen and Windows
- ✓ Body and Chassis
- ✓ Steering and Suspension
- ✓ Wheels and Tyres
- ✓ Brakes components
- ✓ Engines and Drivelines
- ✓ Exhaust Emissions
- ✓ Road Test
- ✗ Service Brake Test: Peak - 75%
Distance - 10m
- ✓ Hand brake test: Peak - 85%
Average - 70%
- ✗ Details of other items rejected: Exhaust System leaks

Inspection comments

Excessive brake pedal travel, less than 20% of travel remains

Details of Failed Inspection

1.2 Seat Belts

- 1.2.1 Original manufacturer's seat belts are missing or replacement belts do not meet the vehicle manufacturer's specifications.
- 1.2.5 When extended, the seat belt sash does not retract (the speed of retraction should not be a cause for rejection unless it affects the overall operation of the seat belt assembly in any way).

2.7 Battery

- 2.7.3 Batteries fitted in enclosed areas (i.e boot, cabin and so on) are not fitted in a sealed container which is adequately vented to the outside of the vehicle.

3.1 Windscreen and Glazing

Privacy statement: The Department of Transport and Main Roads is collecting this information on this form for the purposes of managing the department's vehicle register. This information is authorised or required by the Transport Operations (Road Use Management) Act. The department or its agents usually gives some or all of this information to vehicle insurers, statutory entities, lawyers, insolvency entities, persons involved in vehicle accidents/incidents or vehicle manufacturers or their employees or agents and to or through interstate registration authorities. Your personal details will not be disclosed to any third party without your consent unless required or authorised by law.

- 3.1.7 The area of windscreen swept by the wipers to the right of the centre of the vehicle has bull's-eyes or star fractures more than 16mm in diameter or cracks more than 150mm long which either penetrate more than one (1) layer of the glass in a laminated windscreen or interfere with the driver's vision.
- 3.1.10 Anything is fitted to the windscreen or vehicle that obstructs the driver's vision through the swept area of the windscreen.
- 3.1.13 At least half of the number of windows which are designed to be opened, which must include the driver's window, are not capable of being opened.

SAMPLE