



Queensland Government



# Safety Certificate

Cars or Light Commercial Vehicles  
(up to and including 4.5 tonne RGVM)  
Transport Operations (Road Use Management) Act 1995

## Owner and vehicle details

Vehicle Owner's name and address

BILL BLOGGS  
1 MAIN STREET  
BRISBANE QLD Postcode 4000

Plate number (if applicable) State

123XYZ QLD

VIN/Chassis number

6T9T30ABN10AAB001

Make

HOLDEN

Model

COMMODORE

Body shape

WAGON

Series (for example, EA)

VN

Badge (for example, Longreach Tradesman)

SLX

Number of cylinders/rotors

8

Fuel type (if gas, a current gas certificate is required for registration purposes)

PETROL

No. of doors (incl. hatch)

5

Engine number

ABN10AAB001

### Compliance type

Compliance Plate  Import Plate  Other  Give details

Date on plate Vehicle colour

09/89 SILVER

Seating capacity

5

Left or right hand drive? Tare

Left  Right

1492 KG

GVM (if applicable)

N/A

### Results of inspection

Please indicate Pass  Fail

	First inspection	Final inspection
Identification	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Modifications	<input type="checkbox"/>	<input type="checkbox"/>
Seats and restraints	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Lights and electrical components	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Windscreen and windows	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Body and chassis	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Steering and suspension	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Wheels and tyres	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Brake components	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Engines and drivelines	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Exhaust emissions	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Road test	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Service brake test	Peak	Average	Distance	Peak	Average	Distance
	75%	65%	9 m			

Hand brake test	Peak	Average	Peak	Average
	22%	20%		

## LV-P

Details of other items rejected

Mobile AIS unit - location of vehicle inspection

1 MAIN STREET  
BRISBANE QLD 4000

### First inspection

Odometer reading

Result  123456 KM

Inspection date

28/2/16

Inspection time

9:30 am

Mobile AIS unit odometer reading

98765 KM

Signature of examiner

Examiner's no.

10101

### Final inspection (must not be more than 14 days from date of first inspection)

Odometer reading

Result

Inspection date

/ /

Inspection time

: am pm

Mobile AIS unit odometer reading

Signature of examiner

Examiner's no.

### Inspection Station details

Name and location

SMITHY'S AUTO SERVICE  
100 MAIN ST BRISBANE Postcode 4000

AIS number

0010

Mobile AIS unit registration number

JSA123

### Certification

Approved Examiner - I have inspected the vehicle indicated on this form in strict accordance with the guidelines set out in the Code of Practice Vehicle Inspection Guidelines and have found no defect that would affect its safe use on the road and it meets the requirements of the Transport Operations (Road Use Management) Act.

Inspected by - signature of examiner

J S

Date

28/2/16

Name of examiner (please print)

JOHN SMITH

Examiner's no.

10101

Proprietor - I have ensured that the requirements of the Transport Operations (Road Use Management) Act relating to the issue of this certificate have been complied with.

Issued by - signature of proprietor

J S

Date

28/2/16

Name of proprietor (please print)

JOHN SMITH